




S.R. 743 HYDRAULIC ROAD
VARIABLE WIDTH ROW
DB 027-68
HWY 74 XL-237

RECORD NO. 1811
DB 962 302

± 2000' to
Lamba Road



Notes:

1. Current Owner(s) TWP 16-16: Drillers Service Inc., DB 1170-61
2. TWP 16-16 appears to be in an area designated as Zone X-A, shown on F.E.M.A. Flood Insurance Rate Map, Community Panel 5100020780, effective date 02-04-2005.
3. This survey has been prepared without a title report and does not necessarily include all encumbrances on the property. Utilities and easements not shown may exist.

